



DO NOT attempt to power more than 3 devices, be it sensors or slave packs, from a single power pack.
 3 Devices at 33ma = 100ma

Hubbell Building Automation
 Low Voltage Sensors(devices)
 Requires 33ma each

Hubbell Building Automation
 Low Voltage Sensors(devices)
 Requires 33ma each

3 circuits with 4 sensors



Building Automation, Inc.

DATE: 08 Jan 2004	DWG NO. 3c4sen.dwg	REV A
SCALE	SHEET 1 of 1	